# Westhertzanon Assistance Program

## Work Order (Bid Form)

#### **WORK ORDER INFORMATION**

Work Order Name: WO/18018UE-1840/1

Work Order Type: Weatherization Audit Name: 18018UE-1840

**CLIENT INFORMATION** 

Client Name: Address:

Client ID: 18018UE-1840

Alt. Client ID: Sullivan

<u>AGENCY INFORMATION</u>

Agency: Upper East Tennessee Human Development Agency Agency Phone: 246-6180

Address: 301 Louis Street Fax:

Company Name & License Number: _	
Contractor's Signature:	

#### **COMMENT**

Mobile home 1986 model trailer ha T-11 siding and addition

has rot under one windows (all windows can be caulked inside

trailer has vinyl underpinng and no bad places in bellyboard.

Trailer has shinlge roof and has leak at additon area. (leak cover by tarp)

All windows are double pane.

Kitchen exhaust fan ne to be chanege ou and vented to outside.

Has porches on front and back side of trailer.

50.8pa @ 2816Cfm target 1972 Caulk sink in both bath and kitchen

refrigerator old refurbished.

14' x 40'=980

12' x 10' addition added to trailer

Client Name:
Client ID: 18018UE-1840
Alt. Client ID: Sullivan

Work Order (Bid Form)

Work Order Name: WO/18018UE-1840/1 Report Run On: 4/2/2012 DOE Weatherization Assistant Version 8.6.0

Page 1 of 5

### Measures

Measure i Siu	ing (4' x 5') north side			Componen	ts		ı	nspected
Comment REMO	/E t-11 SIDING AND DES	STROYED	INSU	LATION 4' X	5' SECT	ION		
				Estimated	· 		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	iNSTALL T- 11 siding and insulation	SqFt	20					
1	Misc Material	Each	20					
2	Install 20 sq. ft. of wall insulation	SqFt	20					
2	install wall insulation	Each	20					
Other Detail						7		
			Measur	e Sub Total:			Sub Total:	
Measure 2 Ref	rigerator Replacement			Componen	ts			
							•	nspected
# Material / Labor				Estimated			Actual	nspected
4	Description / Comment	Units	Qty	Estimated Unit Cost		Qty		Total
1	Description / Comment  Any - 18 CU FT refrigerator	<i>Units</i> Each	<b>Qty</b> 1			Qty	Actual	
1	Any - 18 CU FT		_			Qty	Actual	
	Any - 18 CU FT refrigerator	Each	1			Qty	Actual	
1	Any - 18 CU FT refrigerator	Each	1			Qty	Actual	
1	Any - 18 CU FT refrigerator	Each	1			Qty	Actual	
1	Any - 18 CU FT refrigerator	Each	1				Actual	
1	Any - 18 CU FT refrigerator	Each	1	Unit Cost			Actual Unit Cost	

Measure 3 Lighting [Dining][3] Comment				Componen	ts LT4	Inspec		
				Estimated	•	Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Compact Fl13 Watt	Each	3					
1	Compact Fl13 Watt	Each	3					
Other Detail								
						]		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 4 Lig	hting [Kitche][2]			Componen				Inspecte
Measure 4 Lig		Units	Qfv	Estimated		Ofv	Actual	
Measure 4 Lig Comment # Material / Labor	hting [Kitche][2]  Description / Comment Compact Fl13 Watt	<i>Units</i> Each	<b>Qty</b> 2	•		Qty		Inspecte
Measure 4 Lig Comment # Material / Labor	Description / Comment		_	Estimated		Qty	Actual	
Measure 4 Lig Comment # Material / Labor	Description / Comment Compact Fl13 Watt	Each	2	Estimated		Qty	Actual	
Measure 4 Lig Comment # Material / Labor	Description / Comment Compact Fl13 Watt	Each	2	Estimated		Qty	Actual	
Measure 4 Lig Comment # Material / Labor	Description / Comment Compact Fl13 Watt	Each	2 2	Estimated Unit Cost			Actual Unit Cost	
Measure 4 Lig Comment  # Material / Labor 1	Description / Comment Compact Fl13 Watt	Each	2 2	Estimated			Actual	
Measure 4 Lig Comment  # Material / Labor 1	Description / Comment Compact Fl13 Watt	Each	2 2	Estimated Unit Cost			Actual Unit Cost	Ĺ

Report Run On: 4/2/2012

Measure 5 Ligi	hting [Bedroo][3]			Componen	ts LT3			Inspecte
Comment								
				Estimated	<u> </u>	Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
I	Compact Fl13 Watt	Each	3					
	Compact Fl13 Watt	Each	3					
Other Detail								
L								
			Measur	e Sub Total:		,	Sub Total:	
<i>Measure</i> 6 Ligl Comment	hting [Bedroo][3]			Componen	ts LT1			Inspecte
				Estimated				
# Material / Labor		Units	-				Actual	
1	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Actual Unit Cost	Total
	Description / Comment Compact Fl13 Watt	Each	<b>Qty</b> 3		Total	Qty		Total
					Total	Qty		Total
	Compact Fl13 Watt	Each	3		Total	Qty		Total
Other Detail	Compact Fl13 Watt	Each	3		Total	Qty		Total
	Compact Fl13 Watt	Each	3		Total	Qty		Total
	Compact Fl13 Watt	Each Each	3		Total			Total
Other Detail  Field Notes:	Compact Fl13 Watt	Each Each	3	Unit Cost	Total		Unit Cost	Total

Report Run On: 4/2/2012

Comment	oke detector			Componen				Inspecte
		11.16		Estimated			Actual	<b>-</b>
Material / Labor	Description / Comment	Units 	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Labor	Each	1					
	CO monitor	Each	1					
Other Detail								
			Measur	e Sub Total:		] .	Sub Total:	
	tall Kitchen Exhaust Far TWFG std Pg.131 224	1		Componen				Inspecte
Comment Vent to	TWFG std Pg.131 224			Estimated	1	Ofv	Actual	Inspecte
		<b>Units</b> Hour	<b>Qty</b> 1	-		Qty		Inspecte Total
<b>comment</b> Vent to	TWFG std Pg.131 224  Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
Comment Vent to  Material / Labor	TWFG std Pg.131 224  Description / Comment Labor	<i>Units</i> Hour	<b>Qty</b> 1	Estimated	1	Qty	Actual	
Comment Vent to  Material / Labor	TWFG std Pg.131 224  Description / Comment Labor	<i>Units</i> Hour	<b>Qty</b> 1	Estimated	1	Qty	Actual	
Comment Vent to  Material / Labor	TWFG std Pg.131 224  Description / Comment Labor	<i>Units</i> Hour	<b>Qty</b> 1	Estimated	1		Actual Unit Cost	
<b>Comment</b> Vent to	TWFG std Pg.131 224  Description / Comment Labor	Units Hour Each	<b>Qty</b> 1 1	Estimated	1		Actual	
Comment Vent to  Material / Labor	TWFG std Pg.131 224  Description / Comment Labor	Units Hour Each	<b>Qty</b> 1 1	Estimated Unit Cost	1		Actual Unit Cost	

Report Run On: 4/2/2012